

Question 37

Q: Calculation does not converge due to mesh collapsing in the large strain analysis.

A: In the large strain analysis, the calculation of the model having an extraordinarily strain-concentrated portion does not converge.

Change the shape, material, or load conditions to avoid the concentration of strain as much as possible.