

**Q:** What are the four piezoelectricity forms, such as e-form and d-form?

**A:** The piezoelectricity matrix has four entry formats: e-form, d-form, h-form, and g-form.

The d-form is often used to input parameters of piezoelectric ceramic.

The e-form is often used to input parameters of quartz or other single crystals.

The four formats of the piezoelectricity matrix are substantially equivalent and interchangeable.

Please refer to the Femtet help menu below for more information on the four forms of equations.

Home>How to Set Body Attribute, Material Property and Boundary Condition>Material Property Tabs>Piezoelectricity Tabs