🛑 Murata Software

Q: What should be done if the computer is out of memory?

A: To address this issue, you can consider adjusting the mesh size to reduce the number of elements or increasing the memory capacity.