

**Q:** What should be done if you fail to create meshes?

**A:** Select [Use Mesher G1] for the mesher G1 in the [Meshing Control] dialog box and then click [Setting] for detailed settings. If the problem persists, please contact Femtet support center.

Please refer to the Femtet help menu below for more information.  
*Home>Technical Notes>How to Solve Meshing Error>Modeling to Reduce Meshing Errors*