🚺 Murata Software

Q: Why can the wire bodies of imported DXF data not be converted to a sheet body?

A: In such a case, the imported DXF data may include fragmented or minute wire bodies, which can prevent the conversion. You must identify and remove such bodies in the original CAD system.