Question 5



Q: What is the relationship between the compliance matrix and the stiffness matrix?

A: The stiffness matrix [D] is the inverse of the compliance matrix [S].

Please refer to the Femtet help menu below for more information.

Home>Technical Notes>Stress Analysis>Anisotropic Elasticity Matrix